

# Demo JRS Inspection Header



## Excavator - Excavator 1000 HR Service Checklist

### Inspection Details

Report #: HVI1323  
Location: India  
Inspection Date: 12-Jun-2021 04:46 PM  
Inspector Name: RJ

### Vehicle Details

Vehicle Category : truck old  
Vehicle Name : mac 56hg  
Vehicle # : 56552  
VIN #: 000006758  
Meter Reading: 200 Miles  
Model/Year: 2018

### Maintenance Service

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Air dryer Inspect if equipped		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	Coolant filter Replace if equipped		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Rollover protective structure (ROPS) Inspect		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### Additional Note

Inspection Report created

Overall Condition: Excellent Condition

Vehicle Safe to Use: **Yes**

Maintenance Required: No

Vehicle Status: Available



Inspector Signature