

Demo JRS Inspection Header



Excavator - Excavator 2000 HR Service Checklist

Inspection Details

Report #: HVI1324
Location: India
Inspection Date: 12-Jun-2021 04:47 PM
Inspector Name: RJ

Vehicle Details

Vehicle Category : truck old
Vehicle Name : mac 56hg
Vehicle # : 56552
VIN #: 000006758
Meter Reading: 200 Miles
Model/Year: 2018

Maintenance Service

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Gear oil compartments Change oils		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	Hydraulic tank Change oil & filter		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Radiator Change antifreeze except when coolant is ELC When ELC add ELC extender @ 3,000 Hr intervals When ELC add ELC extender @ 6,000 Hr intervals		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Additional Note

Inspection Report created

Overall Condition: Excellent Condition

Vehicle Safe to Use: **Yes**

Maintenance Required: No

Vehicle Status: Available

Inspector Signature