

Demo JRS Inspection Header



Excavator - Excavator 250 HR Service Checklist

Inspection Details

Report #: HVI1321
Location: India
Inspection Date: 12-Jun-2021 04:42 PM
Inspector Name: RJ

Vehicle Details

Vehicle Category : big
Vehicle Name : bunner
Vehicle # : rj20_101
VIN #: 1234
Meter Reading: 501 KM
Model/Year: new

GPS Location

Coordinates : 25.15413388,75.84040264
GPS Address : 1CA, Swami Dayanand Saraswati Rd,
New Jawahar Nagar, Gumanpura, Kota, Rajasthan
324007, India


Maintenance Service

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Air conditioning Verify operation & clean cab filters		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	Air reservoir Drain moisture & sediment, inspect for leaks		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Alarms, indicators, & gauges Verify operation		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4	Back-up alarm & lights Verify operation		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5	Batteries, cables, & terminals Inspect & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6	Brake system Check operation & fill fluid level if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7	Coolant		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8	Cooling system- Inspect for leaks & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9	Engine air filters Inspect & clean		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10	Engine crankcase breather - Inspect & clean		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11	Engine oil & filter - Change		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12	Fan & alternator belts - Inspect & adjust if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13	Fluid Analysis of engine oil		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14	Fuel tank - Drain moisture & sediment, inspect for leaks		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

15	Gear oil compartments - Check for leaks & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16	Glass, doors, latches, & body panels Inspect for damage		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17	Ground engaging tools (GET) & undercarriage Visually inspect		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18	Hydraulic cylinders Inspect for leaks or damage		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19	Hydraulic system - Check for leaks & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20	Intake & exhaust system - Visual check for leaks		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21	Lubricate machine - Service all grease fittings		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22	Machine operation Operational performance check		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
23	Radiator Check coolant level & test antifreeze		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
24	Seat belt Inspect for damage or expiration		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
25	Tires Check inflation pressure & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
26	Transmission & Differential housings - Check oil level & fill if necessary		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Additional Note
Inspection report created

Overall Condition: Excellent Condition
 Vehicle Safe to Use: **Yes**
 Maintenance Required: No
 Vehicle Status: Available



 Inspector Signature