

Demo JRS Inspection Header

Excavator - Excavator 500 HR Service Checklist



Inspection Details

Report #: HVI1322

Location: India

Inspection Date: 12-Jun-2021 04:45 PM

Inspector Name: RJ

Vehicle Details

Vehicle Category : truck old

Vehicle Name : mac 56hg

Vehicle # : 56552

VIN #: 000006758

Meter Reading: 200 Miles

Model/Year: 2018

Maintenance Service

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Engine air filters - Inspect secondary, change primary filter		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	Fluid Analysis of oil compartments & coolant		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Fuel system - Change filter & clean primary bowl & screen		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4	Fuel tank cap & fill screen - Inspect & clean		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5	Hydraulic tank - Change filter & clean screen		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6	Transmission - Change oil & filter, clean breather		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Additional Note

Inspection report created

Overall Condition: Excellent Condition

Vehicle Safe to Use: **Yes**

Maintenance Required: No

Vehicle Status: Available



Inspector Signature