

Demo JRS Inspection Header

Excavator - Excavator Daily Check Checklist



Inspection Details

Report #: HVI1325
 Location: India
 Inspection Date: 12-Jun-2021 04:48 PM
 Inspector Name: RJ

Vehicle Details

Vehicle Category : truck old
 Vehicle Name : mac 56hg
 Vehicle # : 56552
 VIN #: 000006758
 Meter Reading: 200 Miles
 Model/Year: 2018

In cab

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Brakes		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2	First Aid Kit available & Fire Extinguisher in service?		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3	Fuel, oil and water - Are levels sufficiently topped up?		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4	Horn		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5	Mirrors & Windscreen		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6	Steering		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7	Washers & Wipers		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Machine - Provide Photos & Notes for any New Damage

SN	Inspection Item	Note	Good	Repair	Replace	NA
8	Body		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9	Correct Bucket/attachment for job		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10	Fuel / Oil		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11	Radiator Level, Grease points lubricated		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12	Wheel nuts & tyres		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Other

SN	Inspection Item	Note	Good	Repair	Replace	NA
13	For any additional comments please select At Risk - Eg. Info you would like to share with Dispatch or Workshop		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Additional Note

Inspection Report created

Overall Condition: Excellent Condition

Vehicle Safe to Use: **Yes**

Maintenance Required: No

Vehicle Status Available



Inspector Signature