



# Heavy Vehicle Inspection Report

## Excavator - Excavator Pre-use Inspection Checklist

**Report# :HVI1077**

**Date : 22-Dec-2018**

**Vehicle Category** Excavator  
**Vehicle Name** 315F Hydraulic Excavator  
**Vehicle #** HJG 511  
**VIN #** BN23876  
**Meter Reading** 32500 Hours  
**Model/Year** 2008  
**Location** US  
**Inspector Name** Zoe

### Upper

SN	Inspection Checklist	Condition	Note
1	Appearance	Good	
2	Covers & Guards	Good	
3	Glass	Good	
4	Paint & Cab Work	Good	

### Engine

SN	Inspection Checklist	Condition	Note
1	Batteries, Level & Cable Ends	Good	
2	Belts & Hoses	Replace	Need to change Belts for driver seat
3	Display Monitor (Test)	Good	
4	Exhaust System	Good	
5	Fuel System	Good	
6	Hydraulic Hoses & Lines	Good	
7	Hydraulic Level	Good	
8	Oil Level Condition	Repair	Need to add 10 Ltr
9	Swing Gear Case Level	Good	
10	Water Level	Good	

### Attachment

SN	Inspection Checklist	Condition	Note
----	----------------------	-----------	------

1	Anti-Clatter Parts	Good	
2	Bucket Condition	Good	
3	Bucket Teeth	Good	
4	Grease Lines & Fittings	Good	
5	Hammer Point	Repair	Need Repair
6	Hydraulic Cylinder	Good	
7	Hydraulic Lines & Hoses	Good	
8	Pins & Keepers	Good	

**Lower**

SN	Inspection Checklist	Condition	Note
1	Final Drive & Oil Level	Repair	
2	Grease Lines on T.T. Bearings	Good	
3	Idlers & Oil Level	Good	
4	Oil Leaks	Good	
5	Rails	Good	
6	Rollers & Oil Level	Good	
7	Track adjustment	Good	
8	Track Pads	Good	

**Safety Warning & Signs**

SN	Inspection Checklist	Condition	Note
1	Fire Extinguisher	Good	
2	Horn & Travel Alarm	Repair	
3	Key for Ignition	Good	
4	Lights	Replace	Need to replace left tail light
5	Manuals	Good	

Additional Comment

**Overall Condition:** A little wear and good Condition  
**Vehicle Safe to Use:** Yes  
**Maintenance Required:** Yes  
**Maintenance Status:** Available  
**Maintenance Priority:** Normal



**Inspector Signature**